


REVISION LIST

Rev. A: 01 July 2020

- Based on revised site layout (Rev.G)

TREE WORK REQUIREMENTS	
G2, Part of G1 & G5	Remove
T4, T5, T6	Crown lift over site to provide 4m clearance over ground level.



Existing layout & tree locations based on:
 Sitech Surveying Services, Topographical Survey, Ref:12308/18, dated June 2018.

Proposed layout based on:
 Clarendon Homes, Proposed Site Layout, Ref: 20-1091 - PL01 Rev. G

139 Bush Road
 Cuxton
 Rochester
 Kent
 ME2 1EZ
 Tel: 01634 724023
 E-mail: curtis@sylvanarb.co.uk
 Web: www.sylvanarb.co.uk

TREE PROTECTION PLAN
 (Existing Layout / Proposed)

Site Address:
 Land to West of
 70 Church Street
 Boughton Monchelsea
 Maidstone
 Kent
 ME17 4HN
 Client:
 Clarendon Homes

By: C. Barkel
 Date: 15 April 2020
 Ref: CS/TPP/1680-02-A
 Scale: 1:400 @ A1

Key:

- Category A Tree (Green circle)
- Category B Tree (Blue circle)
- Category C Tree (Grey circle)
- Category U Tree (Red circle)
- Retained Tree (Green dashed circle)
- Root Protection Area (White circle)
- Tree to be Removed (Red dashed circle)
- Type 1: Tree Protection Fencing (See Sylvanarb Appdx. B for specification) (Red line)
- Type 2: Tree Protection Fencing (see Sylvanarb Appdx. B for specification) or site boundary fencing/hoarding (Blue line)
- Temporary Ground Protection (See Sylvanarb Appdx. C for specification) (Orange hatched area)